

View Online at <https://aerobasegroup.com/nsn/5210-01-562-3432>

Overall Length:

4.700 inches

Overall Height:

1.100 inches

Overall Width:

2.600 inches

Storage Temperature Range:

-22.0/+158.0 degrees fahrenheit

Unpackaged Unit Weight:

0.440 pounds

Voltage In Volts And Current Type:

3.0 dc

Product Name:

Pd 40 laser range meter

Special Features:

Laser range meter w/provisioning; provides precise measurement from 2 in to 660 ft; measurements accurate to plus or minus 0.04 in; system includes: range meter, hand strap, batteries (2 aa), battery compartment key, measuring extension, operator instructions, and manufacturers certificate; operating temp. Range: 14 to 122 deg. F (-10 to 50 deg. C); storage temp range: -22 to 158 deg. F (-30 to 70 deg. C); measuring functions single and continuous measurement

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fiig:

A23900