

View Online at <https://aerobasegroup.com/nsn/5280-01-219-9784>

**Special Features:**

Gage set, fan disk; set of three plug gages supplied in a metal storage box; after the old bushings are removed, the disk holes are inspected to determine suitability for rework; after the new bushings are installed the bushing bores are inspected to insure a min. Pass through dia. And also a max. Dia. For the initial .100 in. From the outboard faces of the disk of the tf34-ge-100 turbofan engine

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

No

**Fig:**

A23800