

View Online at <https://aerobasegroup.com/nsn/5342-01-324-4509>

Patch Plate Material Thickness:

Between 0.028 inches and 0.035 inches

Material:

Nickel alloy

Fsc Application Data:

Turbine exhaust duct on f100pw0229 engine

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fiig:

A03100