

View Online at <https://aerobasegroup.com/nsn/5820-00-505-1207>

Ac Voltage Rating:

Unable to decode

Frequency Rating:

Unable to decode

Maximum Power Dissipation Rating:

60.0 watts

Accessory Component Quantity:

1 and 1 and 1 and 1 and 1 and 1 and 1 and 1

Furnished Items:

Cabinet cable kit intercom kit power supply chassis remote control chassis sensicon receiver chassis spare fuse and ac outlet panel transmitter chassis

Accessory Controlling Agency:

Motorola inc.

Accessory Identifying Number:

K-8683-a part no. And k-8684 part no. And k-8621-a part no. And p-8464 part no. And p-8066-m part no. And p-8633-a part no. And p-8659-a part no. And p-8692-b part no.

Internal Battery Accommodation:

Unable to decode

Receiver Frequency Rating:

Between 25.0 megahertz and 50.0 megahertz

Transmitter Frequency Rating:

Between 25.0 megahertz and 50.0 megahertz

Frequency Band Type And Quantity:

1 receiving

Frequency Channel Type And Quantity:

1 receiving and 2 transmitting

Emission Type:

F3

Phase:

Unable to decode

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

Yes - demil/mli

Fiig:

T198-b