NSN 5905-01-239-9182

Resistor Assembly - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/5905-01-239-9182

_				
_	lectrica	ı	Acieta	mco.

10.0 kilohms and 10.0 kilohms and 12.4 ohms and 221.0 kilohms and 57.6 kilohms and 0.2 ohms

Resistance Tolerance In Percent:

-2.0/+2.0 and -1.0/+1.0 and -1.0/+1.0 and -1.0/+1.0 and -1.0/+1.0

Terminal Quantity:

2 and 2 and 2 and 2 and 2

Terminal Type:

Wire lead and wire lead

Resistor Power Dissipation Rating In Watts:

0.25 and 0.25 and 0.25 and 0.25 and 0.25 and 0.25

Mounting Method:

Solder

Component Quantity:

1 and 1 and 1 and 1 and 1

Mounting Configuration:

Spaces even for 8 resistors bottom to top, space 1/2/4/5/7/8 used

Component Controlling Agency:

Northrop corp; northrop corp; northrop corp; northrop corp; northrop corp

Component Name:

Fixed film resistor; fixed fil

Component Identifying Number:

RIr07c1002gm part no. And rnc60h1002fr part no. And rnc60h1242fr part no. And rnc60h2213fr part no. And rnc60h5762fr part no. And rnc60h5762fr part no. And rnc60h5762fr part no.

Assembly Construction Method:

Mounted on socket

Component Relationship:

Not matched

Shelf Life:

N/a

Unit Of Measure:

Demilitarization:

No

Fiig:

T172-f