NSN 6130-01-455-3559

Power Supply - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/6130-01-455-3559

A 1	1	/ - 14	D = 11	
Outn	ut v	/oltage	Ratin	a:

12.0 dc pounds per hour wet 2nd power output

Special Features:

Tif backup battery is desired, connect battery to terminals: use "ac fail" terminal to report loss of ac, use "bat fail" terminal to report low or no battery condition; smp7pm is referenced as "power supply/charger" on data sheet

\sim			-
Sh	Δlt	1 11	Δ.
JII	CII		╺.

N/a

Unit Of Measure:

__

Demilitarization:

No

Fiig:

A39900