

View Online at <https://aerobasegroup.com/nsn/6610-00-845-7530>

Scale Quantity:

1

Scale Name:

G unit

Pointer Quantity:

1 and 1 and 1

Pointer Finish:

Nonluminous and nonluminous and nonluminous

Scale Marking And Surface Finish:

Numerals nonluminous err-100

Knob Quantity:

1

Knob Purpose:

Used to set pointers

Pointer Purpose:

Instantaneous acceleration; minus g acceleration; plus g acceleration

Pointer Type:

Acceleration and minus and plus

Mounting Method:

Bezel

Scale Range:

Minus 5.0 g to plus 10.0 g

Scale Smallest Increment Graduation:

0.5 g

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

Yes - demil/mli

Fiig:

T261-a