

View Online at <https://aerobasegroup.com/nsn/6630-01-630-3415>

General Description:

Item measures endothermic and exothermic transitions as a function of temperature; methods include: temperature ramp (heat/cool cycles) or single temperature (isothermal); transitions measured include: glass transition temperature, melting, chrystallization, curing; degree of cure, and heat capacity

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fig:

A23900