

View Online at <https://aerobasegroup.com/nsn/6635-01-035-7807>

Scale Calibration:

0 to 10 degrees

Operation Method:

Manual

Unit Type:

Mechanical

Mounting Method:

Table

Spring Type For Which Designed:

Torsion

Torque Indicating Wrench Usage Feature:

Not included

Spring Travel Gage:

Not included

Special Features:

Measures force applied during overhaul of nha p/n 104ams2, altitude/airspeed indicator, c-17 aircraft

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fig:

T398-h