

View Online at <https://aerobasegroup.com/nsn/6660-01-292-8986>

General Description:

Test temperature circuits; remove the temperature probe from the motor aspirator radiation shield; connect the model 1452 temperature calibrator to the jack in the radiation shield; using the precision resistor tables test the temperature circuits in accordance with the qualification manual; communication between sensor tower and wau model 17b is required for this test (see serd 0045)

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No