

View Online at <https://aerobasegroup.com/nsn/6685-01-538-2281>

Accessory Components And Quantity:

Test gages come with 3 o-rings, ms 29561-018; 3 brass adapters, 1 inch in diam x 0.250 inches thick; 3 o-rings, ms 29561-010; 3 brass fittings 0.625 inch hex x 3.00 inches long; 1 reducer; 1 plug; 1 socket; and 2 gages, mcmaster carr models 4000 k-11 and 4000 k-14 or equiv

Graduation Unit:

3.0 pounds per square inch and 10.0 pounds per square inch

Adjustability:

Nonadjustable

Scale Range:

+0.0/+15.0 pounds per square inch and +0.0/+100.0 pounds per square inch

Scale Name:

Pounds pressure

Pointer Type:

Indicating

Scale Marking:

Test gages in psi

Scale Type:

Meter dial

Scale Smallest Increment:

0.6 pounds per square inch and 10.0 pounds per square inch

Mounting Method:

Plug

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fig:

T179-b