

View Online at <https://aerobasegroup.com/nsn/6710-00-043-0911>

General Description:

Ball bearing part no. 102569 q type 1, bearing disk part no. 101662 q type 1, o-ring iaw ms28775-007 q type 1, shim part no. 421177 q type 1, spindle spacer part no. 101217 q type 1, spindle washer part no. 105903 q type 1, spindle washer feed part no. 103937 q type 1, take-up spindle part no. 101661 q type 1

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No