## NSN 8040-01-480-9023

A23800

Adhesive Patch Repair Kit - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/8040-01-480-9023

view Online at https://aerobasegroup.com/hsh/8040-01-480-9023
End Application:
C-17a aircraft
Component Quantity:
15
Nonsupply Items And Quantities:
Contains mi-15 type v (pre-cured panels, two 4 x 4 in., with mi-15 topcoat applied), mi-15 topcoat (parts a and b) premeasured, dc-1200
adhesion promoter primer, five pair of polyethylene gloves, two spatulas, two acid brushes and lint free cloth
Usage Design:
For repairing damaged mi-15 and topcoat insulation materials up to 72 square inches
Shelf Life:
N/a
Unit Of Measure:
Demilitarization:
No
Fiig: