NSN 8040-01-631-7569

Adhesive Patch Repair Kit - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/8040-01-631-7569

Supply Items And Quantities:

Repair past 2110b/a (50ml), epx plus ii with 2: 1 & 1: 1 plunger, epx plus ii mixing square nozzle gold, 5.2 mm, repair past release liner, polyester tape 8403 green 2inx73 yard, general purpose scotch brite pad, aerospace squeegee, lint free cloth, microcentrifuge tube, cotton tipped applicators, silver marker, utility knife.

Repair paste kit
Shelf Life:
N/a
Unit Of Measure:
Demilitarization:
No

Fiig: A23800

Product Name: