

View Online at <https://aerobasegroup.com/nsn/8120-01-255-7885>

**General Description:**

Working temperature minus 50 deg. Fahrenheit to plus 250 deg. Fahrenheit; working pressure 3000 psi; proof pressure 5000 psi; working gas dry nitrogen; leakage there shall be no external leakage when pressurized to 5000 psi for 2 minutes

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

No

**Fiig:**

A23900