## NSN 1560-01-104-7597

Longeron Repair Kit - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/1560-01-104-7597

End Application:		
F-5e acft		

## **General Description:**

Consist of plate 3, fitting 2, filler 2, hinge, half 2, skin 2, fairing 3, shim 2, miscellaneous hardware; used on upper longeron, fuselage station 194.0 to fuselage station 202.15

Shelf Life:

N/a

**Unit Of Measure:** 

--

Demilitarization:

Yes - demil/mli