NSN 2910-01-058-4349

Treadle Valve Repair Kit - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/2910-01-058-4349

General Description:

C/o the following items, 6 ea no. 10-32 unf, 0.500 in. Lg machine screws; 1 ea pushrod; 1 ea dust boot; 1 ea u-cup piston ring; 1 ea wear ring; 1 ea silicone lubricant; 1 ea control valve; 1 ea 2.487 in. Od by 0.139 in. Wall thk o-ring; 1 ea 0.989 in. Od by 0.139 in. Wall thk o-ring; 1 ea service bulletin

S	h	е	lf	L	if	е	:	

N/a

Unit Of Measure:

--

Demilitarization:

No