

View Online at <https://aerobasegroup.com/nsn/2930-01-530-7308>

**End Application:**

P/n m1066a1

**Component Document Origin:**

Industrial

**Nonsupply Items And Quantities:**

Repair kit includes impeller marked r123395, seal, housing, ball bearing, ring, shaft, and 1 snap ring, p/n a364r

**End Item Source:**

81945

**End Item Name:**

Diesel generator set 135 kw

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

No

**Fiig:**

A23800