

View Online at <https://aerobasegroup.com/nsn/3120-01-545-7870>

**End Application:**

Airfield damage repair kit-3895-01-539-0585/yanmar I70v6 engine-piston assembly

**Product Name:**

Piston pin bushing

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

No

**Fig:**

A045a0