NSN 4320-01-633-2362

Pumping Assembly Repair Kit - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/4320-01-633-2362

Component Quantity:
12
Product Name:
Repair kit 84
Special Features:
Kit contains: 701002 o-ring (6); 98221800 vale cap (6)
Shelf Life:
N/a
Unit Of Measure:
Demilitarization:
No

Fiig: A23800