

View Online at <https://aerobasegroup.com/nsn/4720-01-337-3955>

**Inside Surface Condition:**

Smooth

**Special Features:**

Two brass fittings; two copper seals with 2 groove gaskets; supports the brake line for allis chalmers trucks

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

No

**Fig:**

A542a0