

View Online at <https://aerobasegroup.com/nsn/4720-01-337-3955>

Inside Surface Condition:

Smooth

Special Features:

Two brass fittings; two copper seals with 2 groove gaskets; supports the brake line for allis chalmers trucks

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fig:

A542a0