## NSN 4730-00-003-8323

Pipe Repair Clamp - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/4730-00-003-8323

Clamplength:
6.000 inches
Pipe Size Accommodated:
1.000 inches
Construction Type:
One piece
Material:
Steel nut
Surface Treatment:
Passivate band
Shelf Life:
N/a
Unit Of Measure:
Demilitarization:
No
Fiig:
A12700