NSN 4730-00-003-8323

Pipe Repair Clamp - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/4730-00-003-8323

Clamplength:

6.000 inches

Pipe Size Accommodated:

1.000 inches

Construction Type:

One piece

Material:

Steel nut

Surface Treatment:

Passivate band

Shelf Life:

N/a

Unit Of Measure:

Demilitarization:

No

Fiig:

.

A12700