NSN 4730-01-118-1308

Pipe Repair Clamp - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/4730-01-118-1308

Clamplength:
3.000 inches
Pipe Size Accommodated:
1.250 inches
Construction Type:
One piece
Material:
Stainless steel nut
Shelf Life:
N/a
Unit Of Measure:
Demilitarization:
No
Fiig:

A12700