

View Online at <https://aerobasegroup.com/nsn/4810-01-624-9705>

**End Application:**

4810-01-375-2376

**Component Quantity:**

15

**Component Document Origin:**

Industrial

**Document Source:**

99657

**Document Type:**

Engineering parts list

**Component Document Page Number:**

1

**Supply Items And Quantities:**

1270-00-544-4591, slug, p/n 1046481, 1; 4810-00-737-9837, stem, fluid valve, p/n 135632-0001, 1; 5330-00-349-9436, o-ring, p/n 4420171-0110, 2; 5331-0-292-0577, o-ring, p/n 4420171-0070, 3; 5331-00-640-9613, o-ring, p/n 4420171-0120, 3; 5331-00-554-4665, o-ring, p/n 4420171-0130, 1; 5331-00-554-4675, oring, p/n 4420171-0280, 2

**Nonsupply Items And Quantities:**

Seat assembly, p/n 201892-1, 2

**End Item Source:**

99657

**Document Identification:**

Repair kit for 180442-111

**End Item Name:**

Valve, linear directional control

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

No

**Fiig:**

A23800