NSN 4820-01-515-1578

Valve Repair Kit - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/4820-01-515-1578

Special Features:
Rebuilt kit; contains straight shaft, requires 1725189 straight fit impeller
Shelf Life:
N/a
Unit Of Measure:

Demilitarization:

No

Fiig:

A505x0