NSN 4820-01-605-4232

Valve Repair Kit - Page 1 of 1

A505x0



View Online at https://aerobasegroup.com/nsn/4820-01-605-4232

Component Quantity:
5
Nonsupply Items And Quantities:
1 np6 o-ring washer, 1 np6 r-lower stem, 1 np6 o-ring gland, 1 o-ring 2-010 e540-80, 1 o-ring 2-011 e540-80
Product Name:
Stem/seal repair kit
Shelf Life:
N/a
Unit Of Measure:
Demilitarization:
No
Filg: