NSN 4820-01-608-4507

Valve Repair Kit - Page 1 of 1

A505x0



View Online at https://aerobasegroup.com/nsn/4820-01-608-4507

nd Application:
alve ball
roduct Name:
it, seal
pecial Features:
epair kit for series 84/99/or 60. Kit contains: 2 seats, 2 body seals, 2 stem packings, 2 thrust bearings and belleville washers
helf Life:
/a
nit Of Measure:
emilitarization:
0
lig: