

View Online at https://aerobasegroup.com/nsn/4920-01-291-2559

## **End Application:**

F100-pw-229 engine

## **Special Features:**

Aluminum and steel; company item name-fixture leak check no. 5 bearing compartment corbon seal

## **Functional Description:**

Used as leak check fixture during no. 5 bearing compartment carbon seal repair/maintenance

## **Reference Data And Literature:**

T.O. 2j-f100-94; serd no. 5516; t.O. 33d4-6-512-1

#### Shelf Life:

N/a

## Unit Of Measure:

---

## **Demilitarization:**

No

# Fiig:

A505c0