NSN 5180-01-182-6985

Pylon Skin Repair Kit - Page 1 of 1

No



View Online at https://aerobasegroup.com/nsn/5180-01-182-6985

End Application:
F4, pylon fitting skin
General Description:
Kit includes: countersink gage 3; reamer 4; cutter, hole 26; probe 4; collar 4
Shelf Life:
N/a
Unit Of Measure:
Demilitarization: