NSN 5180-01-182-6985

Pylon Skin Repair Kit - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/5180-01-182-6985

End Application:

F4, pylon fitting skin

General Description:

Kit includes: countersink gage 3; reamer 4; cutter, hole 26; probe 4; collar 4

Shelf Life:

N/a

Unit Of Measure:

Demilitarization:

No