NSN 5180-01-182-6987

Pylon Skin Repair Kit - Page 1 of 1

No



View Online at https://aerobasegroup.com/nsn/5180-01-182-6987

End Application:
F4; pylon fitting skin
General Description:
Major componets: drill motor 1; cutter 3; sanding disk 4; router 8; reamer 7; inspection pin 3; gage 5; router 4
Shelf Life:
N/a
Unit Of Measure:
Demilitarization: