

View Online at <https://aerobasegroup.com/nsn/5220-01-373-0186>

Special Features:

This gage has known defects, and used to perform calibration prior to running f100-229 engine parts, it is a reoperated engine part; used when operator has performed prestart checks on holographic inspection test stand p/n pwa54900; gage master installed on excitation plate when operator sets up test stand for 5th stage compressor stator segment; rqrd prior to performing bond inspection of f100 engine parts; engine p/n 4078485

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fig:

T303-e