NSN 5430-01-313-4595

Fiig: A23800

Collapsible Fabric Tank Repair Kit - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/5430-01-313-4595 **End Application:** Model5ma1196 **Component Quantity:** 50 **Component Document Origin:** Industrial **Document Source:** 03481 **Document Type:** Mfr drawing **Component Document Page Number: Nonsupply Items And Quantities:** Repair kit, consists of: 1 ea 16 oz solvent (mek); 1 ea stitcher; 1 ea scissors; 3 ea brush 1/2 in.; 10 ea mixing cups; 1 ea lid pry; 1 ea buffing cloth; 10 ea repair patch, 3 in. Dia; 6 ea repair patch, 4 in. Dia; 6 ea repair patch, 5 in. Dia; 1 ea fabric strip 4 in. By 72 in.; 1 ea clamp ms27826-1; 1 ea clamp ms27826-2; repair procedure 84-31-044; 1 ea eyedropper **End Item Source:** 03481 **Document Identification:** 1ma1061 **End Item Name:** Tank Shelf Life: N/a **Unit Of Measure: Demilitarization:** No