## NSN 6220-01-466-0877

Lantern-light Repair Kit - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/6220-01-466-0877

Furnished Items:
Reflector assembly and gaskets
End Application:
Nvis for c130
End Item Source:
06097
Special Features:
Bezel and glass lens are not included in kit; assemble making sure 0.062 in. Gasket is centered on reflector assembly and 0.032 in. Gasket
is center inside of bezel
Shelf Life:
N/a
Unit Of Measure:
<del></del>
Demilitarization:
No
Fiig:
A23800