

View Online at <https://aerobasegroup.com/nsn/6910-01-228-5381>

**Identification Designator:**

P-3 integral fuel tank repair procedures

**Artist/sound Recorded:**

Video film

**Recording Date:**

1975

**Special Features:**

Ams rate and related maintenance personnel

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

No

**Fiig:**

T112-f