NSN 9340-01-431-8961

Sight Glass Repair Kit - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/9340-01-431-8961

Overall Length:

32.125 inches

Special Features:

Bulk tank guage repair kit; polytetrafluoroethylene o-rings.

Shelf Life:

N/a

Unit Of Measure:

Demilitarization:

No